

WHAT IS NOT INCLUDED UNDER LIMITED WARRANTY

- 1) AFTER THE FIRST YEAR OF THIS LIMITED WARRANTY, THE FOLLOWING ITEMS ARE NOT COVERED:
 - a. Upper and lower cowlings, gauges / meters, fuel and oil tank, remote control box and external wire harnesses;
 - b. Electrical components (other than ignition and direct fuel injection components);
 - c. Tubes, seals, gaskets, o-rings, plastic or rubber components and fittings.

- 2) THROUGHOUT THE ENTIRE TERM OF THIS LIMITED WARRANTY, THE FOLLOWING ITEMS ARE NOT COVERED:
 - a) Any of the parts, materials or labour costs involved with required or recommended routine maintenance.
 - b) The follow parts:
 - i) Anode, trim-tab, fuel filter ,oil filter, air filter, spark plugs, shear-pin, propeller, propeller hubs, wire cable, drive belt brushes for starter motor and power tilt motor;
 - ii) Rubber goods, including the water pump impeller, fuel hoses, primer bulb assembly and vinyl pipe.
 - c) Damages or failures of the outboard engine resulting from:
 - i) Accident, theft, fire, misapplication or misuse (proper use is described in the Owner's Manual), submersion or freezing due to improper protection / storage;
 - ii) Striking any submerged object;
 - iii) Use of improper, dirty and / or contaminated fuels, fluids or lubricants;
 - iv) Use of parts not supplied or authorised Tohatsu Corporation and or Lakeside Marine Pty Limited;
 - v) Any unauthorised modification or alteration or improper repair;
 - vi) Normal cosmetic deterioration, such as rust, corrosion, fading or decal or paint colour, peeling of paint or decal caused by lack of maintenance or harsh climate conditions;
 - vii) Racing or speed contests;
 - viii) Water entering engine through the fuel intake, air intake, or exhaust system;
 - ix) The use of propeller(s) that do not allow the outboard motor to run in its recommended wide open throttle rpm range.